

CNC – Machining center

DECKEL MAHO DMU 100 T

Moving directions:

X-Axis 1080 mm

Y-Axis 710 mm

Z-Axis 710 mm

B-Axis (+12,5° - 91°)

C- Axis (n x 360°)

32 Tools



CNC- Machining center

XYZ 810VMC

Moving directions:

X-Axis 810mm

Y-Axis 500 mm

Z-Axis 500 mm

20 Tools



CNC- Machining center

DECKEL MAHO DMC 64 V

Moving directions:

X-Axis 640 mm

Y-Axis 600 mm

Z-Axis 500 mm

A-Axis (n x 360°)

30 Tools

